

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section						
Inis section must b	pe completed in its entiret	y to constitute a v	alid maintenance p	permit. This permit i	must be complet	
prior to perf	forming maintenance activ	ities and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance		n for Maintenance:	Rantiu			
Property Address: <u>\frac{1}{2}</u>	327 Molen Arc	MC	Property Owner's 1	Name Stream +	Monn Star	
Municipality: <u>Stl</u>	Wuter zip:550	Property Ide				
Maintenance Permit	No: <u>L3073t 16617</u>				war Sanjica / 146	
				y a chimoninental se	Wel Service/ LTO	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintena	ance Hole (1) Other (20% of greater	
			enter authorization c	ode)		
	ecurely replaced? Yes					
3. Is there evidence	of tank leakage from a se	ptic, holding, preti	eatment or pump	tank below the opera	ating depth or	
evidence of dam	naged, cracked, or structur	ally unsound main	tenance hole cove	ers? 🗌 Yes 🗖 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 $\frac{1}{2}$ $\frac{5}{6}$	gal Tank #2	_gal Pretreatment	tank ga	l Pump Tank	as l	
. Other information	: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns or other	gat	
			and a sure	cy concerns, or other	concerns.	
. Location of septage	e disposal: 82. para 1					
	Dialout	s Environmental S				
	Pinky'	s Environmental Se				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673