

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	mpleted in its entirety to				
	8-8-19 Reason fo				,
Property Address: 468		0	operty Owner's Nan	ne: Deserve	Type
Municipality: After	ZIP: 550	Property Iden	tification Number: _		
Maintenance Permit No:_	23581616174 Ma	intainer Name an	d License No. Pinky's	Environmental Sew	er Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remov	e septage: Maintenanc	e Hole Other (e	nter authorization code	e)	
2. Were all covers securely replaced? ☐ Yes ☐ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? \square Yes \square No					
_	Tank	Leaking Out	Leaking In	Cover Damage	
Se	eptic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No	
Se	eptic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pr	etreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pu	ımp Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of	septage were removed?				
Tank #1 /200 g	al Tank #2	gal Pretreatment	tankgal	Pump Tank	gal
	st any troubleshooting, r - large bush, ca				
6. Location of septage dis	sposal:				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673