

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entiret	y to constitute and	- 14 d 1 - 1			
prior to perfe	e completed in its entiret	ities and romain o	alid maintenance	permit. This permit	must be complet	
	orming maintenance activ			tion of the mainten	ance activity.	
Date of Maintenance	Reaso	n for Maintenance:	Keethill			
Property Address:	NSO 661 St.		Property Owner's	Name: Man Ret	n= UNIVER	
Municipality: PM		Property Ide	entification Numbe	r:	Tuttle	
Maintenance Permit	No:p5562n16138	Maintainer Name a	nd License No. Pin	ky's Environmental S	ewer Service/ L16	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank ——— in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintena	man Hala Poul			TH 25% OF Greater	
			enter authorization c	ode)		
	ecurely replaced? Yes					
ovidence of dam	of tank leakage from a sep	otic, holding, pret	eatment or pump	tank below the ope	rating depth or	
evidence of damaged, cracked, or structurally unsound maintenance hole covers?  Yes						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed	?				
Tank #1 250	gal Tank #2	gal Pretreatment	tank g	al Pump Tank	gal	
. Other information	: List any troubleshooting,	minor repairs cor	ducted tank safe	ty concerns or other	gat	
			dacted, turn sure	ty concerns, or othe	er concerns.	
. Location of septage	disposal: SL Day 1					
	<del></del>					
	Pinky'	s Environmental Se	wer Service Inc			
	Tillky					
		PO Box 35	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673