

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

				And the second s		
This section must be prior to perfo	e completed in its entirety orming maintenance activit	to constitute a vies and remain or	alid maintenance p n-site for the durat	ermit. This permit	must be completed	
Date of Maintenance:	<u>8-2-19</u> Reason	for Maintenance:	Reutine		nee delivity.	
Property Address: <u></u>	GOO Manning H	Tre No	Property Owner's N	lame: Artice &	there -	
Municipality:	y or		entification Number			
Maintenance Permit N	40: X2C81X16181 N					
			11 21 cense 110. 1 111K	y 3 Environmentat se	wer service/ L16/3	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
		= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to ren	nove septage: Maintenan	ce Hole Other (enter authorization co	ode)		
	curely replaced? Yes					
3. Is there evidence	of tank leakage from a sept	ic, holding, preti	eatment or pump	tank helow the oper	ating donth or	
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed?	10.00				
Tank #1 _/(200	_ gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal	
o. Other information:	List any troubleshooting, r	minor repairs cor	ducted, tank safet	y concerns, or other	concerns.	
T00 060 Fe-	manhote					
Location of contage	dianasal					
. Location of septage	disposal:					
	Dinlay's	Environmental Se				
	i iiky s	PO Box 35				

P: 651-439-4847 License Number: L1673

Afton MN 55001