

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

mast be completed in its entiret	y to constitute a v	alid maintenance r	permit This permit r	nust be completed	
This section must be completed in its entirety prior to performing maintenance activity	ities and remain o	n-site for the dura	tion of the maintenar	nce activity	
Date of Maintenance: 8.27-19 Reason	n for Maintenance:	Reethur	sion of the manifemal	nce activity.	
Property Address: 17625 53ml 8	St. No.Ct.	Property Owner's N	Name: Steve M	eens	
Municipality: Stillulto zip: 55	282 Property Ide	entification Number	:		
Maintenance Permit No: <u>Y 3850 b KC 92</u>					
	- Tame	and Electise No. Till	ky s Environmentat Se	wer Service/ L16/3	
Maintenance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Tank — in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintena	ance Hole Other (3	
2. Were all covers securely replaced? Yes		chief authorization c	ode)		
The state of the s					
Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structur	ally unsound main	tenance hale cove	tank below the opera	ating depth or	
		Techanice Hote Cove	13: 🗆 163 🖻 140		
Tank	Leaking Out	Leaking In	Cover Damage		
Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Ves No		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No		
Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☑ No ☐ Yes ☑ No	☐ Yes ☑ No ☐ Yes ☑ No		
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed	Yes No Yes No Yes No Yes No Yes No	☐ Yes ☑ No ☐ Yes ☑ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed	Yes No Yes No Yes No Yes No Yes No	☐ Yes ☑ No ☐ Yes ☑ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	σal	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed Tank #1	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	☐ Yes ☐ No ☐ tankga	☐ Yes ☐ No	gal	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	☐ Yes ☐ No ☐ tankga	☐ Yes ☐ No	gal concerns.	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed Tank #1 5 gal Tank #2 6. Other information: List any troubleshooting,	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No tank ganducted, tank safe	Yes No Yes No Yes No Yes No Pump Tank ty concerns, or other	gal concerns.	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank How many gallons of septage were removed Tank #1	Yes No Yes No Yes No Yes No Yes No Yes No Regal Pretreatment	Yes No Yes No Yes No Yes No Yes No tank ganducted, tank safe	Yes No Yes No Yes No Yes No Yes No Pump Tank ty concerns, or other	gal	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673