

SSTS MAINTENANCE REPORT

System Location		
Address	5980 S. Warner Rd	Telephone Number 651-777-3018
City	Pine Springs	State MN ZIP 55115 Property ID No./GEO Code 050292121 - 0009
Owner	William Feely	Pumping Date
Contractor		
Maintainer	MPCA License No.	Telephone Number

What was done to the system?
<input type="checkbox"/> Tank(s) Pumped <input checked="" type="checkbox"/> Sludge and scum measured. Do tanks need to be pumped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If no provide measurements below)

Report Liquid Capacity in Gallons
Tank 1: _____ <input type="checkbox"/> Pumped Tank 2: _____ <input type="checkbox"/> Pumped Tank 3: _____ <input type="checkbox"/> Pumped Tank 4: _____ <input type="checkbox"/> Pumped Total Gallons Pumped: _____

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.

*Tank Measurements-Use Only if Tank(s) Were NOT Pumped
Liquid Level of Tank (Distance from invert of outlet pipe to bottom of tank): <u>41</u> in. Sludge Level <u>3.5</u> in. + Scum Level <u>2.5</u> in. = Total Sludge and Scum Level <u>6</u> in. Total Sludge and Scum Level <u>6</u> in. / Liquid Level <u>41</u> in. = Sludge and Scum percent in Tank <u>14.6</u> %
<div style="display: flex; align-items: flex-start;"> <div style="flex: 1;"> </div> <div style="flex: 1; padding-left: 20px;"> <p>*Tanks must be pumped if either of the following conditions exist:</p> <ol style="list-style-type: none"> 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity. </div> </div>

Signature William J Feely
 15965917814

Date: 10-20-19

RECEIVED
OCT 23 2019

2019
\$22.00 Processing Fee
 Make Checks payable and remit to:
PUBLIC HEALTH
 Washington County Public Health and Environment
 14949 62nd St N
 Stillwater, MN 55082