

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	y to constitute a v	alid maintenance	permit. This permit	must be completed	
prior to perfo	rming maintenance activi	ities and remain o	n-site for the dura	tion of the mainten	ance activity.	
Date of Maintenance:	9-27-19 Reason	n for Maintenance:	Reutin			
	150 St. Crui				Smer	
Municipality: ACTC		VI Property Ide			201000	
		- Property Ide	ntification number		_	
Maintenance Fermit N	o:1557c16686	Maintainer Name a	nd License No. Pin	ky's Environmental S	ewer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see3. Is there evidence of	curely replaced? Maintena furely replaced? Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, preto ally unsound main	eatment or pump tenance hole cove	tank below the ope	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 5 00	gal Tank #2 500	_gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information:	List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or othe	er concerns.	
6. Location of septage	disposal:					
	Pinlar'	s Environmental So	vor Condes Iss			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673