

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in it		301 S		
prior to porfer	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit	must be complete
prior to perfor	ming maintenance activiti	ies and remain on	-site for the durat	ion of the maintena	ince activity.
Date of Maintenance:	7-25-19 Reason	for Maintenance:	Reutin		
Property Address: 987	CO Perkins Av	c Ma	Property Owner's N	ame: WILLY	Panen
Municipality:	uuto zip: 58				recrucy
Maintenance Permit No	:CITICIGGOTM	laintainer Name ar	nd License No. Pink	y's Environmental Se	ewer Service/ L167
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if n	o provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	urely replaced? Yes tank leakage from a septed, cracked, or structura	ic, holding, pretr	eatment or pump t enance hole cover	ank below the oper	rating depth or
_	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No	
\$	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
ŀ	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1500	septage were removed? gal Tank #2 ist any troubleshooting, r	gal Pretreatment minor repairs con	tankgal	Pump Tank	gal
. Location of septage d	isposal:ST./	7			
	Pinky's	Environmental Sev	ver Service Inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673