## Washington ≋County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 10/0/19 Reason f	or Maintenance: YOUTINI
Property Address: 1493 GYLU (1000 7	12119 Property Owner's Name: Matt RUMAN
Municipality: 01 2018 (1000 ZIP: 560)	U Property Identification Number:
Maintenance Permit No: M	aintainer Name and License NoSchlomka Service LLC/L2989
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)

X Tank(s) Pumped	Liquid Level of Tank in
$\Box$ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater

1. Access used to remove septage: 
Maintenance Hole Other (enter authorization code)

2. Were all covers securely replaced?  $- Yes - No^{-} NA^{-}$ 

3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?

Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	-Yes - No	Yes No	Yes No
Septic/Holding Tank #2	🗌 Yes 🗌 No	□ Yes □ No	🗌 Yes 🗌 No
Pretreatment Tank	🗌 Yes 🗌 No	🗌 Yes 🗌 No	🗌 Yes 🗌 No
Pump Tank	🗌 Yes 🗌 No	🗌 Yes 🗌 No	🗆 Yes 🗌 No

4. How many gallons of septage were removed?

Tank #1 <u>   (J UU      </u> gal    Tank #	2 gal Pretreatment tank gal Pump Tank	gal
5. Other information: List any trou	bleshooting, minor repairs conducted, tank safety concerns, or other (	concerns.
NO MH LOCATEd WMPZE	d through pipe forme antwers unknown	
5. Location of septage disposal:	Metro	,

Schlomka Services, LLC. 1303 Frontage Rd S Suite 135 Hastings, MN 55003 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.