

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

<u>prior</u> to performing maintenance a	tirety to constitute a v	alid maintenance	permit. This permit	must be completed	
Date of Maintenance: 9-23-19 R	according and remain o	To the dura	tion of the mainten	ance activity.	
The state of the s					
Property Address: 255 Omcuho	1 Ave Mc	Property Owner's I	Name: Eric N	crestrem	
Municipality: Stillulto ZIP:	SSOSZ Property Ide	entification Number	:		
Maintenance Permit No: S61701673				ewer Service/ L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Liquid Level of Tank ———				,	
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurement		= % Sludge & Scum Tanks must be pumped if 25% or greater			
evidence of damaged, cracked, or stru ————————————————————————————————————	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 250 gal Tank #2	gal Pretreatment	tankga	l Pump Tank	σal	
Tank #1 250 gal Tank #2 Other information: List any troubleshood	gal Pretreatment	ducted, tank safet	ry concerns, or othe		
Tank #1 250 gal Tank #2  . Other information: List any troubleshood  . Location of septage disposal:	gal Pretreatment	nducted, tank safet	ry concerns, or othe	r concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673