

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a va	lid maintenance p	ermit. This permit	must be completed	
prior to performing maintenance activ					
Date of Maintenance: 9-20-19 Reaso					
Property Address: 13115 50t St.			lame: Aften (	Pere Centre	
~ ( )	Property Ide				
Maintenance Permit No: <u>17964</u> 17668					
The state of the s	Maintainer Name a	id Licerise No. Filik	s s Environmental se	wer Service/ L167.	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank — in				
$\square$ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Mainten	ance Hole Other (e	enter authorization co	ode)		
2. Were all covers securely replaced?   Yes					
<ol><li>Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu</li></ol>	eptic, holding, pretr			ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	d?				
Tank #1 / 000 gal Tank #2 / 1000	gal Pretreatment	tankga	al Pump Tank	gal	
5. Other information: List any troubleshooting	g, minor repairs cor	ducted, tank safe	ty concerns, or othe	r concerns.	
6. Location of septage disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673