

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	rmit. This permit	must be completed	
	rming maintenance activit					
Date of Maintenance:	<u>9-19-19</u> Reason	for Maintenance:	Partine			
Property Address: 17	60 Merell Are	- Man Pr	operty Owner's Na	me: Marge	wazlawik	
Municipality: <u>SMN</u>		82 Property Iden				
Maintenance Permit N	10:16273c16569 M	laintainer Name and	d License No. Pinky	's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers se Is there evidence 	nove septage: Maintenan curely replaced? Yes of tank leakage from a septaged, cracked, or structura	□ No tic, holding, pretre	eatment or pump t enance hole cover	ank below the oper s?		
	Tank ————————————————————————————————————	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1500	of septage were removed? gal Tank #2 /> >>> List any troubleshooting,	gal Pretreatment	tankgal	Pump Tank y concerns, or othe	gal gal concerns.	
6. Location of septage		,				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673