

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location

Address 680 No	el Aug S		*		Teleph	one Number		
City Affan		State	UZIP 5	500/	Property ID	No./GEO Code		
Owner M. Ke His	ks	Pumping (Date 10/	3/15				
		Co	ntractor					
Maintainer MEYER S	EWER	MPCA Lice	nse No.	915	Teleph	one Number 65	1-459-016	
What was done to the system?			Report Liquid Capacity in Gallons					
Tank(s) Pumped			Tan	Tank 1: / Pumped Tank 2: Pumped				
Sludge and scum measured.			Tan		Pum		Pumped	
Do tanks need to be pumped? Yes No (If no provide measurements below)			Total Gallons Pumped: 10000					
Visual Inspection (note ar	· · · · · · · · · · · · · · · · · · ·		N	OTE: This	does not s	erve as a compl	iance inspection.	
			·					
1	ent ent							
JAN (9 6 2016							
								
I last time to the	*Tank Measure	ments-Use (Only If Tar	ık(s) Were î	NOT Pumpe	ed		
Tank Length in. X	Tank Width	in. X Tan	nk Depth	in,	= Tank V	olume (cubic inch	es)	
Tank Radius in. X	Tank Radius	in. X 3.	14 = Ta	nk Volume ((cubic inche	es)		
Tank Volume (cu. in.)	/ 231.01 = Li	quid Capacit	ty	Gallon	is / Tank De	pth in. = G	allons/Inch	
Sludge Level in. X	Gallons Per Inch	= Sludg	ge Volume	G	allons			
Scum Level in. X	Gallons Per Inch	= Scum	o Volume	G	allons			
Sludge Volume +	Scum Volume	= Total	Sludge an	d Scum Vol	ume	Gallons		
Total Słudge and Scum Volu	me/ Lic	quid Capacity	у	= Perce	ent Sludge a	and Scum in Tank	<u>~~~</u>	
Scum Layer Effluent Sludge Layer			from inve	th measured t of outlet ottom of tan	follov 1. The 12 ind baffle 2. Tot	ches from the bot e; or tal sludge and scu 25 percent of the	xist: e layer is less than tom of the outlet m volume is greater	
Signature	ignature					Res	set Form	