

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

**System Location** 

Address 1872 Stage coach Tr5			Telephone Number	Telephone Number	
City After	State MA	1 ZIP 55001	Property ID No./GEO Code		
Owner Waryle	Blonger's + Pumping D	ate 10/1/15			
	Соп	itractor			
Maintainer MEYER SEW	IER MPCA Licen	se No. 915	Telephone Number 65	1-459-016.	
What was done to the system?		Report Liquid Capacity in Gallons			
Tank(s) Pumped		Tank 1: 1500	Pumped Tank 2:	Pumped	
Sludge and scum measured.  Do tanks need to be pumped?	ì	Tank 3:	Pumped Tank 4:	Pumped	
Yes No (If no provide measurements below)		Total Gallons Pumped: 1500			
Visual Inspection (note any prob	olems with the system):	NOTE: This	does not serve as a compli	ance inspection.	
			ECEIVED		
			- JAN <b>06</b> 2016		
			•		
	T-144	PH.	The second of th		
^	Tank Measurements-Use O				
Tank Length in. X Tank	Width in. <b>X</b> Tanl	k Depth in.	= Tank Volume (cubic inche	25)	
Tank Radius in. <b>X</b> Tank	Radius in. <b>X 3.1</b>	4 = Tank Volume	cubic inches)	•	
Tank Volume (cu. in.) / 231.01 = Liquid Capacity Gallons / Tank Depth in. = Gallons/Inch					
Sludge Level in. <b>X</b> Gallor	ns Per Inch = Sludg	e Volume G	allons		
Scum Level in. <b>X</b> Gallor	ns Per Inch = Scum	Volume G	allons		
Sludge Volume + Scum	Volume = Total 9	Sludge and Scum Vol	ume Gallons		
Total Sludge and Scum Volume	/ Liquid Capacity	= Perce	ent Sludge and Scum in Tank -	%	
Scum Layer  Effluent  Sludge Layer		Fank Depth measured from invert of outlet pipe to bottom of tan	than 25 percent of the t	ist: layer is less than om of the outlet m volume is greater	
Signature	Da	te	Rese	et Form	