

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
	rming maintenance activity			on of the maintena	nce activity.	
Date of Maintenance:	10-22-19 Reason	for Maintenance:	MATINA			
Property Address: 3	520 Bailey	Rel	Property Owner's Na	ame: Leny	Hores	
Municipality: <u>HCU</u>	pca zip:550	S Property Ide	entification Number:		-	
Maintenance Permit N	10: F3807 m 17015	Maintainer Name a	nd License No. Pinky	r's Environmental Se	ewer Service/ L167:	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	move septage: Maintena	nce Hole Other (enter authorization cod	deltooold		
2. Were all covers se	curely replaced? Yes	No				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed					
Tank #1 15 ===	gal Tank #2	_gal Pretreatmen	tankgal	Pump Tank	gal	
	: List any troubleshooting,					
-						
		/				
6. Location of septage	e disposal:					
	District					
	Pinky	s Environmental Se	ewer Service Inc.			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673