

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

	/ 2 / M				ance activity.	
Date of Maintenance:	$\frac{7/2/8}{600}$ Reason	for Maintenance:	Routin	2		
Property Address:	2100 Manne	ing thees	Property Owner's N	Name: Mark	Stard	
Municipality:	2 //	//	ntification Number	,		
Maintenance Permit N	No: Sol86214939				AND THE PROPERTY OF THE PROPER	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater				
2. Were all covers se	nove septage:  Maintena curely replaced?  Yes of tank leakage from a sep aged, cracked, or structur	□No			erating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes 🖾 No	☐ Yes ♠No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1500	of septage were removedgal Tank #2	_gal Pretreatmen	tankg	al Pump Tank	gal	
Montole	: List any troubleshooting, - 4. Lt. deep	, illinor repairs col	iducted, tank sare	ety concerns, or oth	er concerns.	
6. Location of septage	e disposat:					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162