## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 8/33/17 Reason	for Maintenance:/	Maintenance P	umping		
. 38		perty Owner's Name:	lichael Lee		
Municipality: Hugo	State MN Zip Co	de <u>55038</u> GEO C	ode/Property I.D. #: 12/15	18020	
What was done to the system?	Tank M	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Lieudh e elekt			•	
Sludge and scum measured.	Liquid Level of Ta	ank in. Sludge	Level in. Scum Level	in. 	
Do tanks need to be pumped?	Total (Sludge + S	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum			
Yes No (If no provide measuremen	nts)				
1. Access used to remove septage: Mainte			<ul> <li>* Tank must be pumped if t is greater than 25%.</li> </ul>	nis value	
2. If maintenance hole was used, were all cover	s securely replaced?	Yes No please exp	lain	10	
Explanation:		•			
3. If owner refuses to allow a Subsurface Sew them complete and sign the following stat	vage Treatment Systement:	em (SSTS) to be pumped	through the maintenance hole	, have	
l, (o	wner's name), refuse to	o allow the removal of soli	ds and liquids through the main	tenance	
hole. I understand that removal of solids and					
4. Is the tank designed as a leaky tank? example	: seepage pit, cesspool,	drywell, leaching pit			
Tank#1 Yes No Verificatio Method	Used:				
Tank#2 Yes No Verificatio Method	Used:				
<ol> <li>Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound</li> </ol>			ow the operating depth or evi	dence of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes 🕅 No	☐ Yes ☑ No		
Septic/Holding Tank #2	☐ Yes 📉 No	☐ Yes IXNo	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes IXNo	☐ Yes ☐No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	□ Yes □ No		
6. How many gallons of septage were remove	ed?	Shop tank			
Tank #1 750 Tank #2 950	Pretreatment T	10 10 10 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1	mp Tank		
7. Other information: List any troubleshootin	g, minor repairs cond	lucted, tank safety conce	rns, or other concerns.		
3. Certification: I hereby certify as a State of Mi and made the observations, or					
Maintainer's Name: 05005 Scale	~ Serwic Maintain	er's Address: \7639	s Lyons STNE	٠,	
Maintainer's License #: 216 Maintain	ner's Phone #: 65	16/64/2082 Fore	st lake, MN 550	25	
Maintainer's Signature		Date: &	•		