DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-00067 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10/25/2019Re	ason for Maintenance	100001	M1	
Property Address: 23540 Nunicipality: Scanding	loulan Ana	49870j1	1279	
Municipality: Grandia	State MAI / 7in	Code Code	Loren & Carol Hubin	
What was done to the system?	21	Code <u>58073</u> GE	O Code/Property I.D. #:	
Tank(s) Pumped	Tani	Tank Measurements (must be completed if tanks NOT pumped)		
Sludge and scum measured.		Liquid Level of Tank in. Sludge Level in c		
Do tanks need to be pumped? Yes No (If no provide measure)	Total (Sludge	Total (Sludge + Scum)		
1. Access used to remove septage: Main		.,		
2. If maintenance hole was used, were all con	vers securely replaced:	ner (Go to #3 below)	 * Tank must be pumped if this value is greater than 25%. 	
explanation.				
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Sys	tem (SSTS) to be number	4.4	
l.				
	(owner's name), refuse	to allow the removal of so	lids and liquids through the maintenance	
hole. I understand that removal of solids ar 4. Is the tank designed as a leaky tank? examp	nd liquids through othe	er access points is not cons	idered maintenance	
	- seepage pit, cesspoo	, drywell, leaching pit	ndered maintenance.	
Tank#1 Yes No Verificatio Metho	d Used:	T		
Tank#2 Yes No Verificatio Metho	1/3 09	1		
5. Is there evidence of tank looking	a used: Visce	1/		
5. Is there evidence of tank leakage from a s damaged, cracked, or structurally unsoun	eptic, holding, pretre d maintenance bole	atment or pump tank be	low the operating depth or swiden as	
Tank		F.	achtil of Evidence of	
Septic/Holding Tank #1	Leaking Out Yes No	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	Yes No	Yes - No	
Pretreatment Tank	Tyes TNo	Yes No	Yes No	
Pump Tank	Yes Divo	Yes No	Yes No	
6. How many gallons of septage were remove	d?	Yes No	Yes T.No	
Tank#1 1,000 Tank#2 1,000		nk		
7. Other information: List any troubleshooting	nimer remain	Pui	mp Tank ———————	
7. Other information: List any troubleshooting				
8. Certification: Thereby certify as a State of Min	2000000			
8. Certification: I hereby certify as a State of Mir and made the observations, or of Maintainer's Names.	directly supervised of the	Maintainer that I personally	conducted the work	
Maintainer's Name: 0551		and the bellottilatice of t	inis job.	
Maintainer's License #: Maintaine	er's Phone #: Yuy.	r's Address: 10638	Lyns St. NE	
Maintainer's Signature				
Date: 10/25/2015				