## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730



## **SSTS MAINTENANCE REPORT**

Date of Mainten	ance 9/6/2019 Reason	n for Maintenance:	> 29491/69	358		
Property Addres	is: 75// 190th 2	S+ Prope	Property Owner's Name: Dick Mary Reinte			
Municipality:	orest Lake			ode/Property I.D. #:		
What was done to the system?		Tank Mea	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Yes No (If no provide measurements)		Liquid Level of Tanl  Total (Sludge + Scu			in. *	
1. Access used to	remove septage: 🛴 Maint	enance Hole Other (G	io to #3 below)	* Tank must be pumped if this v	alue	
	e hole was used, were all cove			is greater than 25%. <b>Iain</b>		
Explanation:						
3. If owner refus them complet	es to allow a Subsurface Se e and sign the following sta	wage Treatment System Itement:	(SSTS) to be pumped t	through the maintenance hole, ha	ve	
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance						
	and that removal of solids an			dered maintenance.		
4. Is the tank desi	igned as a leaky tank? <i>exampl</i>	e: seepage pit, cesspool, dry	well, leaching pit			
Tank#1 ☐ Ye	es 🖘 No Verificatio Metho	d Used:				
Tank#2 □ Ye	es No Verificatio Metho	d Used:				
			nont or name to be	ow the operating depth or eviden		
damaged, crae	cked, or structurally unsoun	d maintenance hole cov	ers?	ow the operating depth or eviden	ce of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No		
Septic/Holding Tank #2		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
6. How many gal	lons of septage were remov	red?				
Tank #1 _ <i>130</i> @	Tank #2	Pretreatment Tan	Pretreatment Tank Pump Tank			
. –	tion: List any troubleshooti	ng, minor repairs conduc	cted, tank safety conce	erns, or other concerns.		
8. Certification:	I hereby certify as a State of N and made the observations, o	Ainnesota certified SSTS M or directly supervised othe	aintainer that I personal rs in the performance of	lly conducted the work f this job.		
Maintainer's Na	ime: OSSI	Maintainer'	Maintainer's Address: 17638 Lyons St NE			
Maintainer's Lic	cense #: 2/6 Mainta	iner's Phone #: <u>65</u> /	-464-2082			
Maintainer's Sig	gnature 855 T	200	Date: 9	16/19		
				· 1		