DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

PO

SSTS MAINTENANCE REPORT

Date of Maintenance $915/9$ Reason for	Maintenance:	6694×16854	l .	
Property Address: 12375 Upger 14	leafled Prop	erty Owner's Name:		
Municipality: HUZU S	tate MZip Cod	e 55039 GEO	Code/Property I.D. #:	
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tai	nk in. Sludg	e Level in. Scum Level	in.
Do tanks need to be pumped? Yes No (If no provide measurements)	Total (Sludge + Sc	um) / Liquid I	Level = % Sludge & Scum	
1. Access used to remove septage: Maintenan	ce Hole Cother	(Go to #3 below)	 Tank must be pumped if this value is greater than 25%. 	/alue
2. If maintenance hole was used, were all covers se	curely replaced?	≯es		
Explanation:	•			
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem	e Treatment Syster ent:	n (SSTS) to be pumpe	d through the maintenance hole, ha	ive
I, (own	er's name), refuse to	allow the removal of so	olids and liquids through the mainten	ance
hole. I understand that removal of solids and liq	uids through other a	access points is not con	sidered maintenance.	
4. Is the tank designed as a leaky tank? example: see	epage pit, cesspool, d	rywell, leaching pit		
Tank#1 🗀 Yes 🔀 No Verificatio Method Us	ed: V15 V2	(
Tank#2 Yes Vo Verificatio Method Us	ed: Nisun	. (
5. Is there evidence of tank leakage from a septi damaged, cracked, or structurally unsound m	c, holding, pretrea	tment or pump tank b	elow the operating depth or evider	nce of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes Sto	☐ Yes ☐ No	
Septic/Holding Tank #2	Yes No	Γ Yes চ⊀√No	Yes No	
Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed?				
Tank #1 1500 Tank #2 1000	Pretreatment Ta	nk	Pump Tank 100	
7. Other information: List any troubleshooting,	minor repairs cond	ucted, tank safety cor	ncerns, or other concerns.	
8. Certification: I hereby certify as a State of Minn and made the observations, or di	esota certified SSTS rectly supervised otl	Maintainer that I personers in the performance	nally conducted the work e of this job.	
Maintainer's Name: DSS Maintainer's License #: D Maintainer	Maintaine	er's Address: 176	38 Lyons St. UE	
Maintainer's License #: 216 Maintainer	's Phone #: <u>(6)-</u>	464-2082	×	
Maintainer's Signature		Date:	915/2019	