## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Data after	1 /21		- HANGE NEP	)KI		
Date of Mai	intenance 1029/19	Reason fo Maintenance:	2 Campliana	A 93110 101 0		
Property Address: 6640-725th St. No Property Owner's Name:						
Municipality	r:			Thomas Krey		
Wha	at was done to the system?			EO Code/Property I.D. #:		
Tank(s) Pe		lank	Measurements (must b	e completed if tanks NOT pu	impod)	
		Liquid Level of	CT- 4		mipeu)	
Sludge and scum measured.  Do tanks need to be pumped?		- dain Fedel Di	in. Slu	dge Level in. Scum Le	vel in.	
Yes	No (If no provide measur	rements) Total (Sludge +	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum			
1. Access used	to remove septage: Mi	aintenance Holo	- 10			
= · · · · · · · · · · · · · · · · · · ·	nce noie was used, were all c	overs securely replaced?	er (Go to #3 below)  Yes Mo please (	* Tank must be pumpe is greater than 25%. explain	d if this value	
Explanation						
3. If owner ref	uses to allow a Subsurface	Sewage Treatment Syst	om (SETS) As Is	d through the maintenance		
them compt	ete and sign the following	statement:	to be pumpe	d through the maintenance	hole, have	
1,		lownorle				
hole. Lunder	stand that removal of solids	and liquids through the	to allow the removal of s	olids and liquids through the n	naintenance	
4. Is the tank de	stand that removal of solids signed as a leaky tank? exam	ond iiquids through other	r access points is not con	sidered maintenance.	anneng nee	
		rici scepage pit, tesspool,	drywell, leaching pit			
rank#1   i y	es No Verificatio Metl	nod Used:				
Tank#2 TY	es No Verificatio Man					
		lod Used:				
damaged, cra	ence of tank leakage from a	septic, holding, pretrea	itment or pump tank h	elow the operating depth or		
	cked, or structurally unsou	ind maintenance hole co	ers?	now the operating depth or	evidence of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	Yes No			
	Septic/Holding Tank #2	Yes No	T Yes T No	Yes No		
	Pretreatment Tank	TYes TNo		Yes TiNo		
	Pump Tank	Yes No	Yes No	T Yes No		
6. How many gal	lons of septage were remove	fin les l'IMO	Yes No	☐ Yes ☐ No		
	or septage were remov	ved?				
Tank #1 1468	Tank #2	Pretreatment Tar	ak n.			
7. Other informat	ion: List any troubleshooti	no main an	··· Pl	Imp Tank		
	ion: List any troubleshooti	ng, minor repairs condu	cted, tank safety conce	rns, or other concerns.		
a a	hereby certify as a State of N nd made the observations, o	linnesota certified SSTS N	laintainer that I personal	V conducto del		
		r directly supervised othe	ers in the performance of	this job.		
Maintainer's Nam	ne: OSSI				21	
Maintainer's Lice	nco 4.6 3.1			Lyns St. 1	JE	
	Maintai	ner's Phone #: 4u4-	2080	(		
Maintainer's Signature						
<b>3</b>	Date:					