DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENTGOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance (1-7-19 Reason for Maintenance: 7-2433;17693					
Property Address	s: 460 235 th St	Property Owner's Name: Mars & Harry Hartung			
Municipality:	S	tate Zip Code	GEC	Code/Property I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements)		Liquid Level of Tan Total (Sludge + Scu		<u> </u>	in. -
1. Access used to	remove septage: Maintenan	ce Hole Other (0	Go to #3 below)	 Tank must be pumped if this is greater than 25%. 	/alue
2. If maintenance	hole was used, were all covers se	curely replaced?	Yes No <i>please e</i>		
Explanation:		(
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement: (owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance. 4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit Tank#1					
		Yes No	Yes No	Yes No	
64	lons of septage were removed?				
Tank #1 1400	Tank #2	Pretreatment Tar	nk	Pump Tank	
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.					
Maintainer's Na	mme: OSW Sure	Maintaine	r's Address: 763	I Lyans STIF.	
Maintainer's License #: Amaintainer's Phone #: 651464 2082					
Maintainer's Signature Date: 11-7-19					