DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11-7-9 Reason for Maintenance: p9204a17694				
Property Address: 12510 ST Cto X TR Property Owner's Name: 50 e Lubi 12				
Municipality: 51/1 water State Zip Code 55082 GEO Code/Property I.D. #:				
What was done to the system?	Tank Me	Tank Measurements (must be completed if tanks NOT pumped)		
☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurement)	Total (Sludge + Sc	Liquid Level of Tank in. Sludge Level in. Scum Level in. * Total (Sludge + Scum) / Liquid Level = % Sludge & Scum		
1. Access used to remove septage: Maintenance Hole : Other (Go to #3 below) * Tank must be pumped if this value				
is greater than 25%. 2. If maintenance hole was used, were all covers securely replaced? Yes No please explain Explanation:				
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:				
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids and liquids through other access points is not considered maintenance. 4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
Tank#1 Yes No Verificatio Method Used:				
Tank#2 Yes No Verificatio Method Used:				
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	Yes No	Yes No	
5. How many gallons of septage were removed?				
ank #1 Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
3. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.				
Maintainer's Name: 0551 Maintainer's Address: 17638 4/045 57 No. For ATLA				
Maintainer's License #: Maintainer's Phone #: \(\frac{5}{-4/64} \rightarrow \frac{7}{2082}				
Maintainer's Signature Date: 1/-7-/9				