

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GÖVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed Differ to performing maintenance activities and remain on-site for the duration of the maintenance activity.

roperty Address	SILS Reason	n for Maintenance:	3 year			
- shared work day	- 1 9	514 No. 5hac	Property Owner's I	Name:		
Municipality:	mozifiets 5		entification Number		v. Joh	
Maintenance Permit N	10: M9821 V14699	Maintainer Name a	nd License No. Olse	n's Sewer Service/L21	6	
<u>१८११</u> ०८चन्द्र	rice "Pandocritic	Total Meza	र्वाट्याच्या (१८१३) क	र व्यक्तनंत्रसम्बद्धाः १ स्टब्स्ट	C): 6)6(23[c]=[6]	
Tank(s) Pumped Sludge and scum measured			Liquid Level of Tankih Studge Level in Tank, in Scum Level in Tank, in Studge + Scum / Liquid Level X 100			
		Sludge Level in				
Do tanks need to		- 9 Studion & Co		nks must be pumped if	25% or greater	
☐ Yes ☐ No (if	no provide measurements				, : 7	
. Access used to rei	move septage: Mainten	ance Hole Other (enter authorization c	ođe)		
. Were all covers se	ecurely replaced? Yes	□No			i "	
	of tank leakage from a se		reatment or pump	tank below the operat	ting depth or	
evidence of dam	aged, cracked, or structu	rally unsound main	tenance hole cove	ers? 🗆 Yes 🖼		
	Tank	Leaking Out	Leaking In	Cover Damage	•	
*	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes DINo	☐ Yes ☐No		
				00		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
ł. How many gallons	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☑ No	•	
!. How many gallons Tank #1_\\000	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☑ No	? gal	
Tank #1_\\00	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☑ No ☐ Yes ☑ No	3	
Tank #1\500	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☑ No ☐ Yes ☑ No	3	
Tank #1_\\00	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 :: List any troubleshooting	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☑ No ☐ Yes ☑ No	3	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082