

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GÖVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed phior to performing maintenance activities and remain on site for the duration of

		ries and selligiti of	ishe in the bird	tion of the maintena	nce activity.
Date of Maintenance: 5 20 19 Reason for Maintenance: Maintenance					
Property Address: 2390 Award M. W. Property Owner's Name:					
Municipality: 100t dolu ZIP: 550 Property Identification Number:					
Maintenance Permit No: n 5008 e 14702 Maintainer Name and License No. Olson's Sewer Service/L216					
CHOS. S SCHOOL SETS					
હૈંકનોલેલ્વક <b>્</b>	etece Mundojnystaio	Totals Mezo	त्रशीसम्बद्धाः । वर्षासम्बद्धाः ।	- वज्रतनंत्रम्यः विकास	YEEL b) bloggetteb)
☐ Tank(s) Rumped		Liguid Level of Fankin			
Studge and soum n	neasured	Studge Level in Tank in Scum Level in Tank in Studge + Scum / Liquid Level X 100			
Do tanks need to be pumped?  Yes \( \text{No (if no provide measurements)} \)  Studge \( \text{Scum} \)  Studge \( \text{Scum} \)  Tanks must be pumped if 25% or greated to be pumped if					
La les Li No (if	no provide measurements)				190
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced?  Yes  No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes No					
3	Tank	Leaking Out	Leaking in	Cover Damage	•
4	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ⊠No	☐ Yes ⊠No	
-	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?  Tank #1_1250 gal Tank #2 gal Pretreatment tank gal Pump Tank gal  5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage disposal: Met Council					

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082