

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

14949 62nd STREET NORTH P O. BOX 6 STILL WATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	nce: 6-26-19 Rea	son for Maintenance			
	17742 Keyston	e Ave	Property Owner's	Name: Roter	Ander son
lunicipality:	ZIP:	5038 Property to	leptification Numb	ar:	
laintenance Per	mit No: h 1046 Z 15961	_ Maintainer Name	and License No. Ol	son's Sewer Service/L	216
ra income		- C			
	generales assumentation	Tank de	Maria de la Carra	State of the state	Mile bungari
Tankis) Rump	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)				Constraint Constraint
Studge and so		Stugge Level in	Tankir	Scum Level in Tank	fn
Do tanks nee	d to be pumped?	Studge • Scum	/ Liguid	Level X 100	
☐ Yes ☐ N	o (if no provide measurement	ts)	eum	anks must be pumped	if 25% or greate
Access used to	remove septage: Mainte	nones Mela [7 Duba-			
			(enter authorization (códe)	
were all cover	rs securely replaced? A Ye	s Lino	•		•
evidence of c	nce of tank leakage from a s lamaged, cracked, or struct	eptic, holding, prei	reatment or pump	tank below the oper	ating depth or
			ntenance note cov	ers? Yes No	
	Tank	Leaking Out	Leaking in		
			realing in	Cover Damage	<i>:</i>
	Septic/Holding Tank #1	☐ Yes ☒ No	☐ Yes ☐ No	☐ Yes ☐ No	<i>:</i>
**					<i>f</i>
- 157 - 157	Septic/Holding Tank #1	☐ Yes ☒ No	☐ Yes ☐No	☐ Yes ☑No	f = 1000 8000
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☑ No☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	:
K.	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☑ No☐ Yes ☐ Yes ☐ No☐ Yes ☐ Yes	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	f
How many gallo	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were removed	☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	: (#1
Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Pons of septage were removed gal Tank #2	☐ Yes ☒ No ☐ Yes ☐ No d? — gal Pretreatment	☐ Yes ☐ No	☐ Yes ☐ No	:
Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Pons of septage were removed gal Tank #2	☐ Yes ☒ No ☐ Yes ☐ No d? — gal Pretreatment	☐ Yes ☐ No	☐ Yes ☐ No	gal concerns.
Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were removed	☐ Yes ☒ No ☐ Yes ☐ No d? — gal Pretreatment	☐ Yes ☐ No	☐ Yes ☐ No	gal concerns.

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082