

DEPARTMENT OF PUBLICALE ALTHORD ENVIRONMENT

14949 62nd STREET NORTH P 0 3 6 X 6 3 1 1 WATER, MN 55082-000 Office: 651-430-6655 1747 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatmen System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed permit to performing maintenance activities and remain on site for the duration of the maintenance activity.

Date of Maintenan	te: <u>%-7-19</u> Rea	son for Maintenant			With activity.
Property Address:		ve N	Property Dwner's	Name: Fr-C	Sasten
Municipality:	0.1.0		dentification Numb	er:	
Maintenance Perm	it No: <u>CO64/1/6367</u>	Maintainer Name	and License No. o	sinks Sewer Service/L	286
		en juli		THE THE	- 4 / A - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -
Province and	489444 Vilodojantes II Abrillandojantes	raine at	Malfanda (1911) Se complete soc	a casina Fan	स्तिः विभावतद्वे
Ankls) Fumpe Disludge and sour Do tanks need Di Yes DiNo	n measured	Sludge + Scum	7 Liguid	Scum Level in Tarik Level X 100 anks must be pumped :	•
1. Access used to I	remove septage: Mainte	nance Hole III Oshor	Parada ya kina katala ka 19	4. Wi b	
 Were all covers Is there evidence 	securely replaced? 🗹 Yese of tank leakage from a s maged, cracked, or structi	s CNo eptic, holding, oréi	reatment at aumo	tank halow the energy	ating depth or
3	Tank	teaking Out	de Contun	Cover Damage	:
	Septic/Holding Tank #1	☐ Yes ☑No	□ es No	☐ Yes ☐ No	
145 25	Septic/Holding Tank #2	☐ Yes ⊠No	☐ Yes ☑ No	☐ Yes ØNo	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	*
	Pump Tank	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☐No	
Tank #1_/	s of septage were removed gal Tank #2 (OOO) n: List any troubleshooting	_ gal Pretreatment	tank ga iducted, tank safet	I Pump Tank 25	gal gal concerns.
Location of septag	ge disposal: St Po	and My	w (w		

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082