DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10/17/19 Re	ason for Maintenance	h1807r17	1278		
Property Address: 11835 Imper			<u> </u>		
Municipality: Hugo		Code	Stephen & Mary Ro	islo	
What was done to the system?		55038	EO Code/Property I.D. #:		
Tank(s) Pumped	Tani	Tank Measurements (must be completed if tanks NOT pumped)			
Sludge and scum measured.	Liquid Level	/- .		ipea)	
Do tanks need to be pumped?	1 20,010	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Yes No (If no provide measurer	nents) Total (Sludge	+ Scum) / Linux			
1. Access used to remove septage: Timair	otenanca Hola Ciavi			_	
2. If maintenance hole was used, were all cov	remance Hole JOth	ner (Go to #3 below)	* Tank must be pumped	if this value	
Evalance:	rers securely replaced?	Yes No please e	is greater than 25%.		
3. If owner refuses to allow a Subsurface Se them complete and sign the following st	ewage Treatment Sys	tem (SSTS) to be pumpe	d through the maintenance		
f,					
hole. I understand that removal of a tit.	owner's name), refuse	to allow the removal of se	olids and liquids through the mai		
hole. I understand that removal of solids an 4. Is the tank designed as a leaky tank? example	d liquids through othe	er access points is not con	sidered maintenance	intenance	
· · · · · · · · · · · · · · · · · · ·	-r y - Pry CC3300001	drywell, leaching pit			
Tank#1 Yes No Verificatio Method	d Used:				
Tank#2 Ti Yes PNo Verificatio Method					
5. Is there evidence of the tart.	Used:				
5. Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound	ptic, holding, pretre	atment or pump tank he	low the energy		
Tank	maintenance hole c	overs?	on the operating depth or evi	idence of	
Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #2	Yes Dono	Yes No	Yes PNo		
Pretreatment Tank	Yes No	T Yes KNo			
	T Yes T No	Yes No	T Yes ATNO		
Pump Tank	Yes No	Yes No	T Yes T No		
6. How many gallons of septage were removed	i?	2 100 [_:140	☐ Yes ☐ No		
Tank#1 1,000 Tank#2 1,000	Pretreatment Ta	nk n.			
7. Other information: List any troubleshooting	minorromai	Pu	mp Tank		
	millor repairs condu	icted, tank safety concer	ns, or other concerns.		
8. Certification: Thereby certify as a State of Mi					
8. Certification: I hereby certify as a State of Mini and made the observations, or d	resota certified SSTS N	laintainer that I personally	Conducted the worl		
Maintainer's Name		Perior marice of (riis job.		
055 I	Maintainer	s Address:			
Maintainer's License #: 216 Maintainer	's Phone #: 651-4	s Address: 17638 L	yous St N.E.		
Maintainer's Signature	1001-7	1-2082			
OSSI		Date: 10/1	17/19		
		10/1	411		