

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entiroty	to constitut			The state of the s
prior to perfe	e completed in its entirety	ios and remain	alid maintenance p	ermit. This permit	must be completed
Data CH :	orming maintenance activit	ies and remain o	n-site for the durat	tion of the maintena	ince activity.
Date of Maintenance	: <u>//-25-19</u> Reason	for Maintenance:	Boutine		
Property Address: /	RO40 18th St N		Property Owner's N	lame: Bob Sel	wast.
Municipality: Lake	E/MO ZIP: 5504	ta Property Id	entification Number		
Maintenance Permit	No: LNOIZIA MERU	Dintaines No.		•	
/	No: W0121g 17924 N	iairtainer Name a	and License No. Pink	y's Environmental Se	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ——— in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rea	move septage: Maintenand				1 25% of greater
2. Were all covers se	ecurely replaced? Yes	No.	enter authorization co	ode) J DNR 1	ine scoping
evidence of dam	of tank leakage from a sept	lly unsound mair	reatment or pump	tank below the oper	ating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1500	gal Tank #2g	gal Pretreatment	tank ga	Pump Tank	gal
5. Other information:	: List any troubleshooting, r	ninor repairs cor	ducted, tank safet	v concerns or other	gal
		•	, raint surce	y concerns, or other	concerns.
6. Location of septage	disposal:	21			
	Pinky's	Environmental Se	wer Service Inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673