

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	Reason Reason	for Maintenance:	Reg Mans	5	
Property Address: 20	490 July 4	e X/	Property Owner's N	ame: Lane	Browne
Municipality: Fore	H LK ZIP:5502	~	ntification Number		
1	1/5/17				
Maintenance Permit No	0:16217C1 M	laintainer Name ai	nd License No. <u>Smil</u>	ie's Sewer Service/L	.2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped☐ Sludge and scum measured☐ Do tanks need to be pumped?		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: $\square$ Maintenan	nce Hole Other (	enter authorization co	ode) Pre /	978
3. Is there evidence of	curely replaced?  Yes of tank leakage from a sepon ged, cracked, or structurations.	tic, holding, pret			rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☐No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_\\$00_	of septage were removed? gal Tank #2 SOO	gal Pretreatmen			

Smilie's Sewer Service PO BOX 100

Scandia, MN 55073

License# 2428 P: 651-433-3934