

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ety to constitute a v	alid maintenance	permit. This permit	must be complete	
Date of Maintenance: 11-22-19 Reas	on for Heint	Do the dura	tion of the maintena	ance activity.	
11003			Name: XXXXX	Sen Co.to	
Municipality: Stillutto ZIP: 55	OST Dranget II	rroperty Owner's	name:	an anne	
Maintenance Permit No: F7145v17914	Maintainer Name a	and License No. <u>Pin</u>	r: ky's Environmental Se	 ewer Service/ L167	
				2107.	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurement	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a securely replaced? Yes evidence of damaged, cracked, or structue Tank	eptic, holding, pret	reatment or pump stenance hole cove Leaking In	tank below the operers? Yes No Cover Damage	rating depth or	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed Tank #1 250 gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal	
	g, minor repairs cor	nducted, tank safe	ty concerns, or othe	r concerns.	
5. Location of septage disposal:	de Fandania				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673