

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entiret	V to constitute a	-1:-1	752 00 00 0		
prior to per	be completed in its entiret	ritios and remain	alid maintenance	permit. This permit	must be completed	
Data Citi	forming maintenance activ	ities and remain of	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	ce: 11-22-19 Reaso	n for Maintenance:	Kartine			
Property Address:	91825 Ottunion	CA Are No	Property Owner's	Name: Celleer	Gregg	
Municipality: <u>Stl</u>		082 Property Ide			00	
Maintenance Permi	+ NOC 6774017915	Marin :				
	t NOC6724917915	Maintainer Name a	nd License No. Pin	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank ——— in Sound to the Tank				
Do tanks need to be pumped?		Sludge + Scum	Cludge + Cours —			
$\square$ Yes $\square$ No (if no provide measurements)			Sludge + Scum			
				inks must be pumped	if 25% or greater	
. recess used to h	emove septage:   Maintena	ance Hole Other (e	enter authorization c	ode)		
	securely replaced? Yes					
3. Is there evidence	e of tank leakage from a sep	ptic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
evidence of dar	maged, cracked, or structur	ally unsound main	tenance hole cove	ers? 🗌 Yes 🖾 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallon	s of septage were removed	?				
Tank #1 5	gal Tank #2	gal Protroatment	tank			
	gat Talik #Z	_gat Fredreatment	talik ga	l Pump Tank	ادم	
. Other information	gal Tank #2 n: List any troubleshooting,	minor repairs con	ducted, tank safet	V concerns or other	gal	
o. Other information	n: List any troubleshooting,	minor repairs con	ducted, tank safet	y concerns, or other	gal concerns.	
	T. List ally troubleshooting,	minor repairs con	ducted, tank safet	y concerns, or other	concerns.	
	T. List ally troubleshooting,	minor repairs con	ducted, tank safet	y concerns, or other	concerns.	
	The List ally troubleshooting,	minor repairs con	ducted, tank safet	y concerns, or other	concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001