

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	to constitute a v	alid maintenance p	ermit. This permit m	nust be complet
	ming maintenance activiti			ion of the maintenan	ice activity.
Date of Maintenance:	11-13-19 Reason f	for Maintenance:	Boutine		
Property Address: 5	160 Hilltop	Ave n	Property Owner's N	lame: Bruce B	eek
Municipality: Lake	E/mo ZIP: 5504	Property Ide	ntification Number		
Maintenance Permit N	0:X8123x17769M	aintainer Namo a	nd License No. Divi	1. 5	
7	A OI ZOI TITO I MI	anitalilei Naille a	nd License No. Pink	y's Environmental Sev	ver Service/ L16
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
$\square$ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of evidence of dama	f tank leakage from a septi ged, cracked, or structural Tank	ic, holding, preto ly unsound main Leaking Out	reatment or pump tenance hole cove Leaking In	rs? Yes No Cover Damage	iting depth or
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	f septage were removed?	and Dreatment	tank		
Tank #1 /500	gal Tank #2g	gat Pretreatment	talikga	Pump Tank	gal
5. Other information:	List any troubleshooting, n	ninor repairs cor	ducted, tank safet	y concerns, or other	concerns.
Tank your po	List any troubleshooting, n	ninor repairs cor	ducted, tank safet	y concerns, or other	concerns.

PO Box 354

Afton MN 55001