

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	h				idirec remit	
prior to por	be completed in its entired	ty to constitute a v	alid maintenance	permit. This permit	must be completed	
to per	Torring maintenance activ	ities and remain o	n-site for the dura	tion of the maintena	ince activity.	
Date of Maintenanc	re: 11-5-19 Reason	on for Maintenance:	Pantiu	2		
Property Address:	3245 Mean F	tre No	Property Owner's	Name: Sue H	eins	
Municipality: Municipality:	Julitor ZIP: 55	2 Property Id	entification Numbe	r·		
Maintenance Permit	t No: <u>F8702e17749</u>	Maintainer Name	and linear N. Bi			
		maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		The second of the second second second	Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
	if no provide measurements		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintena	ance Hole Other	enter authorization c	odate All		
2. Were all covers	securely replaced? \(\subseteq \text{Yes} \)	□ No.	200000000000000000000000000000000000000	ode 17 68 27 8		
evidence of dan	e of tank leakage from a se naged, cracked, or structur	ally unsound mair	tenance halo cove	tank below the oper	ating depth or	
			- Tote cove	ris: L res L No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	s of septage were removed	?				
Tank #1 _ 5 00	gal Tank #2 _/Dob	_gal Pretreatment	tankga	l Pump Tank	σal	
Other information	n: List any troubleshooting,	minor repairs cor	ducted, tank safet	v concerns, or other	Concerns	
			41	, and a second	concerns.	
		/				
. Location of septag	e disposale					
	e disposat.					
	c disposat.			The state of the		
		s Environmental Se	wer Service Inc.			
		s Environmental Se PO Box 35				

Maintenance activities must be reported to the Department within 90 days.

Pl 65T-439-484/ License