

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	must be complete	
prior to performing maintenance activ	ities and remain o	n-site for the dura	tion of the mainten	ance activity	
Date of Maintenance: 1-5-19 Reaso	n for Maintenance:	Ruhu	1	and detivity.	
Property Address: 13870 23rd S		-	Anchia	* Clina:	
Municipality: Stillwater zip:55	282 Property Ide	entification Numbe	r:	Avelatter	
Maintenance Permit No: 1251 lg 17214	Maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service / I 1673	
9		_		ewer servicer E1073	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Tank — in			
$\square$ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintena	ance Hole Other (				
2. Were all covers securely replaced? Yes					
<ol><li>Is there evidence of tank leakage from a sep</li></ol>	otic, holding, pret	reatment or pump	tank below the open	rating depth or	
evidence of damaged, cracked, or structur	ally unsound main	tenance hole cove	ers? 🗌 Yes 🖪 No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No			
		_ 165 _ 110	Yes No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank  Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	☐ Yes ☐ No				
Pump Tank  4. How many gallons of septage were removed:  Tank #1 / See gal Tank #2 / Occo	☐ Yes ☐ No ? _gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	۷al	
Pump Tank  4. How many gallons of septage were removed:  Tank #1 / See gal Tank #2 / Occo	☐ Yes ☐ No ? _gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Pump Tank  4. How many gallons of septage were removed	☐ Yes ☐ No ? _gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal r concerns.	
Pump Tank  4. How many gallons of septage were removed:  Tank #1 gal Tank #2 coco  5. Other information: List any troubleshooting,	Yes No ? _gal Pretreatment minor repairs cor	Yes No Yes No tank ga	Yes No Yes No Pump Tank ty concerns, or othe	r concerns.	
Pump Tank  4. How many gallons of septage were removed:  Tank #1 gal Tank #2 coco  5. Other information: List any troubleshooting,	Yes No ? _gal Pretreatment minor repairs cor	Yes No Yes No tank ga	Yes No Yes No Pump Tank ty concerns, or othe	r concerns.	
Pump Tank  How many gallons of septage were removed  Tank #1	Yes No ? _gal Pretreatment minor repairs cor	Yes No Yes No tank ga	Yes No Yes No Pump Tank ty concerns, or othe	r concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673