

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

<u> </u>						
Date of Maintenance: 1/15/18 Reason for Maintenance: Rottline						
Property Address: 16060 6th St. M. Property Owner's Names Stave Kunde						
Municipality: Lakelana ZIP: Property Identification Number:						
Maintenance Permit No: h5743w/3877 Maintainer Name and License No. M55-1915						
	B (1	Tank Mose	Tank Measurement (must be completed if tanks NOT pumped)			
Maintenance Performed						
✓ Tank(s) Pumped☐ Sludge and scum measured		Liquid Level of Tank in				
		III -	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum 7 Equid Level x 100				
☐ Yes ☐ No (if no provide measurements)		Ja stadge a set	70 Strage & Scarri Tanks must be pumped if 2500 of greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Z Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	<u> </u>					
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes Z No	☐ Yes Ø No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 <u>/ 600</u> gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
Junged thru binch pipe oldertank.						
6. Location of septage disposal:						

Meyer Sewer Service, Inc. 5325 Manning Ave 5 Afton, MN 55001 License# 915 P: 651-459-0162