

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	or manifectionice.	Routin		
Property Address: 11157 73 74 St. 5		Property Owner's N	lame: Tom Ri	unning
Municipality: (offuge Grove ZIP: 5501	Property Ide	ntification Number	water to	
Maintenance Permit No: 185279/066 Ma	aintainer Name a	nd License No. 🕍	Majer L915	5
25084e4761		<i>y</i>		
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Tank in		
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be numbed if 25% or greater			
Do tanks need to be pumped?				
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance	e Hole 💋 Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? Yes				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes 🎵 No	☐ Yes ☑ No	☐ Yes ☑No	
Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	
Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	φal
Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 gal Tank #2 gal	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal er concerns.
Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	Yes No Yes No Yes No Pretreatment	Yes No Yes No Yes No tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank ety concerns, or oth	gal er concerns.

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162