

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location							
Address 1230	New Ave N			Telephone N	lumber		
City Lake Eli	<i>~</i> e	State MN ZIF	55042 PI	operty ID No./G	EO Code		
Owner Marth	Twomey	Pumping Date	4/28/15				
Contractor							
Maintainer MEYE	R SEWER	MPCA License No	915	Telephone N	lumber 651-4	159-0162	
What was		Report Liquid Capacity in Gallons					
Tank(s) Pumped		Tank 1: 1500 Pumped Tank 2: 1000 Pumped					
Sludge and scum n		Tank 3: 1500	Pumped	Tank 4:	Pumped		
Do tanks need to b		Total Gallons Pumped: 4000					
Yes No (If no provide measurements below)							
Visual Inspection (n	ote any problems with the	system):	NOTE: This d	oes not serve	as a compliance	inspection.	
			122 January 1222				
			JAN 0 5 2016				
			J	MIA 09 7010			
			A THE STATE OF THE	9.4			
	*Tank Measure	ments-Use Only II	f Tank(s) Were N	OT Pumped/			
Tank Length	in. X Tank Width in. X Tank Depth in. = Tank Volume (cubic inches)						
Tank Radius	in. X Tank Radius	in. X 3.14 =	Tank Volume (c	ubic inches)			
Tank Volume (cu. in.)	/ 231.01 = Li	iquid Capacity	Gallons	/ Tank Depth _	in. = Gallons	/Inch	
Sludge Level	in. X Gallons Per Inch	= Sludge Vol	ume Gal	llons		. :	
Scum Level	in. X Gallons Per Inch	= Scum Volu	me Gal	llons			
Sludge Volume	+ Scum Volume	= Total Sludg	ge and Scum Volui	me	Gallons -		
Total Sludge and Scu	m Volume / Lic	quid Capacity	= Percer	nt Sludge and So	tum in Tank	% ———	
Scum Layer		Tank	Depth measured	*Tahks must be pumped if either of the following conditions exist: 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or			
Sludge Layer		from	invert of outlet to bottom of tank	than 25 ne	2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.		