## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance $12-4-15$ Reason for	Maintenance: G	Routin	2	
Property Address: 10931 3rd St	Property (	Owner's Name:	ary olson	
Municipality: Lake Elmo St	tate MN Zip Code _		e/Property I.D. #:	
What was done to the system?	Tank Measur	ements (must be comp	pleted if tanks NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured. ☐ Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements)	Liquid Level of Tank  Total (Sludge + Scum)	in. Sludge Lev	<del></del>	in. *
1. Access used to remove septage: Maintenar	nce Hole Gother (Got	to #3 below)	* Tank must be pumped if this v is greater than 25%.	alue
2. If maintenance hole was used, were all covers se			=	
Explanation:				
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem		STS) to be pumped the	rough the maintenance hole, ha	ve
l, (own	er's name), refuse to allo	ow the removal of solids	and liquids through the maintena	ance
hole. I understand that removal of solids and lic	uids through other acce	ess points is not conside	red maintenance.	
4. Is the tank designed as a leaky tank? example: se	epage pit, cesspool, dryw	ell, leaching pit		
Tank#1 Yes No Verificatio Method U	sed:			
Tank#2 Yes No Verificatio Method U	sed:			
5. Is there evidence of tank leakage from a sept damaged, cracked, or structurally unsound n	tic, holding, pretreatme	ent or pump tank belo /s?	w the operating depth or evide	nce of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	T Yes T No	T Yes F-No	☐ Yes ☐ No	
Septic/Holding Tank #2	T Yes T No	☐ Yes ☐ No	Yes No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	☐ Yes ☐ No	TYes No	
6. How many gallons of septage were removed	?			
Tank #1 /500 Tank #2	Pretreatment Tank Pur		mp Tank	
7. Other information: List any troubleshooting	, minor repairs conduc	ted, tank safety conce	rns, or other concerns.	
8. Certification: I hereby certify as a State of Min and made the observations, or of Maintainer's Name: PINKY'S SEWER SERVICE	nesota certified SSTS Ma directly supervised other Maintainer's	rs in the performance of	ly conducted the work this job. Afton, MN 55001	
	er's Phone #: 651-439-4			
Maintainer's Signature	China	 Date: /2	2-4-15	