

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

		System Lo	cation			
Address 8845 27th SFN			Telephone Number			
City & Lake &	Ehmo	State My Z	PS 5042) Prop	erty ID No./GEO Code		
Owner Dawel	Mexer	Pumping Date	8/28/15			
		Contrac				
Maintainer MEY	ER SEWER	MPCA License N	0. 915	Telephone Number 65/	-459-0162	
What was done to the system?			Report Liquid Capacity in Gallons			
Tank(s) Pumped			Tank 1: /500 2	Pumped Tank 2:	Pumped	
Sludge and scum measured.			Tank 3:	Pumped Tank 4:	Pumped	
Do tanks need to be pumped?						
Yes No	(If no provide measurement	s below)	Total Gallons Pumpe	ed: <u>/5/00</u>		
Visual Inspection (note any problems with t	the system):	NOTE: This doe	s not serve as a complia	nce inspection.	
				JAN 05 Z016		
			Son	இதி இனை நிருவை சும் மணவர் மணவர் மணவர் நிறுவர்கள்	5794 ⊓ Ş	
	*Tank Measu	rements-Use Only	lf Tank(s) Were NOT	Pumped		
Tank Length	in. X Tank Width	in. X Tank De	pth in. =	Tank Volume (cubic inches)	
Tank Radius	in. X Tank Radius	in. X 3.14 =	= Tank Volume (cubi	ic inches)		
Tank Volume (cu. in.	/ 231.01 =	Liquid Capacity	Gallons / 1	Fank Depth in. = Gallo	ons/Inch	
Sludge Level	in. X Gallons Per Inch	= Sludge Vo	lume Gallor	ns		
Scum Level	in. X Gallons Per Inch	= Scum Volu	ıme Gallor	ns		
Sludge Volume	+ Scum Volume	= Total Slud	ge and Scum Volume	Gallons		
Total Sludge and Sci	um Volume /	Liquid Capacity	= Percent S	lludge and Scum in Tank	% 	
Scum Layer Effluent Sludge Layer		from	Depth measured invert of outlet to bottom of tank	*Tanks must be pumped following conditions exis 1. The top of the sludge land inches from the bottom baffle; or 2. Total sludge and scum than 25 percent of the tacapacity.	t: ayer is less than m of the outlet volume is greater	