

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

<u>prior</u> to perior	ming maintenance activit	ties and remain on	-site for the durat	ion of the mainten	ance activity.	
Date of Maintenance:	7/14/18 Reason	for Maintenance:	Routine	)	$\mathcal{O}$	
Property Address:	6590 7th	St.S	Property Owner's N	lame:	Ilhomoson	
Municipality: La	keland/ZIP: 55	042Property Ide	ntification Number	: 7//	7113319	
Maintenance Permit N	o: d 4244×5154	Maintainer Name a	nd License No.			
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes \( \sum \) No (if no provide measurements)		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to rem	nove septage:   Maintena	nce Hole 🔀 Other (e	enter authorization c	ode)		
	ourely replaced? Yes of tank leakage from a sep ged, cracked, or structur		reatment or pump tenance hole cove Leaking In	tank below the opers?  Cover Damage	erating depth or	
	Septic/Holding Tank #1					
		☐ Yes ☒No	☐ Yes ØNo	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 /500	of septage were removed _ gal Tank #2 List any troubleshooting	gal Pretreatment, minor repairs con	nducted, tank safe	al Pump Tank ty concerns, or oth	gal er concerns.	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162