## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance (2-22-15 Reason for Maintenance: ROLLING					
Property Address: 9490 1004 SEN Property Owner's Name: RIAMA DECLY					
Municipality: Still wester State My Zip Code GEO Code/Property I.D. #:					
What was don	e to the system?	Tank Meas	urements (must be o	ompleted if tanks NOT pump	ed)
Tank(s) Pumped Sludge and scum m Do tanks need to be	pumped?	Liquid Level of Tank  Total (Sludge + Scu		<del></del>	*
	no provide measurement		- 4- #2  - 12	* Tank must be pumped	if this value
1. Access used to remove septage: [ Maintenance Hole 2 Other (Go to #3 below) is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Tes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
damaged, cracked,	Tank	Leaking Out	Leaking In	Cover Damage	
Sept	ic/Holding Tank #1	Yes No	☐ Yes ► No	Yes The	-
	ic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	•
Preti	reatment Tank	Yes No	Yes No	☐ Yes ☐ No	_
Pum	p Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	_
6. How many gallons of septage were removed?					
Tank #1 1000 Tank #2 1000 Pretreatment Tank Pump Tank					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
7. Other morniation.	miscury irodoscomo				
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.					
DO Pay 354 Afron MN 55001					
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 334 Arton, Win 33001					
Maintainer's License #: 1673 Maintainer's Phone #: 651-439-4847					
Maintainer's Signatu	ire <u>Ale</u>	4/_	Date:	12-22-15	
		1/			