

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

			Sys	tem Loca	ation				***************************************
		110th	54.	5			Telephone	Number	
City Hasty	193		State 7	n/VZIP	550	23 Prop	erty ID No./	GEO Code	
Owner Robert Jager Pumping Date 12/14/15									
				Contract	or /				
Maintainer MEY	er se	WER	MPCA Lic	cense No	91.	5	Telephone	Number 65	1-459-0162
What was done to the system?				Γ		Repo	rt Liquid Ca	pacity in Gal	lons
Tank(s) Pumped Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Yes No (If no provide measurements below)					Tank 3:		Pumped Pumped ed: /5		Pumpec Pumpec
Visual Inspection (note any p	oroblems with	the system):		NOTE:	This doe	s not serve	as a compli	ance inspectior
		*Tank Meas	urements-Use	e Only if	Tank(s) \	Vere NOT	Pumped		
Tank Length	in. χ Ta	ank Width	in. X T				•	e (cubic inche	25)
Tank Radius	in, X Ta	nnk Radius	in. X 3	3.14 =	Tank Vo	 lume (cubi	c inches)		<u> </u>
Tank Volume (cu. in.)	<u></u>	/ 231.01 =	Liquid Capa	city		Gallons / T	ank Depth	in. = Gal	llons/inch
Sludge Level	in. X Ga	illons Per Inch	= Slu	dge Volu	me	Gallon	S		
Scum Level	in. X Ga	ilions Per Inch	= Scu	ım Volum	ne	Gallon	S		
Sludge Volume		um Volume	= Tot	al Sludge	and Scu	— m Volume		Gallons	
Total Sludge and Scu	ım Volume	/	Liquid Capac	ity	 =	Percent Si	udge and S	cum in Tank	%
Scum Layer Effluent Sludge Layer				from in	Depth me overt of o o bottom	utlet	following: 1. The top 12 inches baffle; or 2. Total sit	conditions exi of the sludge from the bott	layer is less than om of the outlet n volume is greats