## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 114 20 Reason f	or Maintenance:	mplimer de	p. Pemit d736/w1800	
Property Address: 13798 Identated Ass. Property Owner's Name: Cobort Keifer				
Municipality:	State Zip Coo	le GEO Co	ode/Property I.D. #:	
What was done to the system?	Tank Me	Tank Measurements (must be completed if tanks NOT pumped)		
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Measurement	Liquid Level of Ta  Total (Sludge + So			
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below)  * Tank must be pumped if this value is greater than 25%.				
2. If maintenance hole was used, were all covers			<del>-</del>	
Explanation: & Compeliance	/			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:				
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
Tank#1 Yes No Verificatio Method	Used: Word			
Tank#2 Yes No Verificatio Method		<sup>\(\)</sup>		
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes KNo	Yes No	Yes XVo	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remove	d?			
Tank #1 Store Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooting	g, minor repairs cond	lucted, tank safety conce	erns, or other concerns.	
1001-		Marinanin ayah at I manana	the according to a defending the	
8. Certification: I hereby certify as a State of Mi and made the observations, or				
Maintainer's Name: OSST	Maintain	er's Address: 1763	3 W. f. 2 snaps s	
Maintainer's License #: Maintain	ner's Phone #: (35)	444-2082		
Maintainer's Signature	Clark	Date:	14-20	