DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

7	leason for Maintenance:	P 250661	7683	
Property Address: 5080 180	h St	Property Owner's Name:	Linda Colemon	1
Municipality:				
What was done to the system?		200	EO Code/Property I.D. #:	
Tank(s) Pumped	Tank	Tank Measurements (must be completed if tanks NOT pumped)		
Sludge and scum measured.	Liquid Level o	(- .		paniped)
Do tanks need to be pumped?	- Adula FeASI	in. Sluc	lge Level in. Scum	Level in.
Yes No (If no provide measure	Total (Sludge	+ Scum) / Linuit		
1. Access used to remove septage: Ma				
2. If maintenance hole was used, were all co	over a long JOH	ner (Go to #3 below)	 * Tank must be pum is greater than 25% 	ped if this value
2. If maintenance hole was used, were all continued to the Explanation:	overs securely replaced?	PYes No please e	explain).
3. If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Sys statement:	tem (SSTS) to be pumpe	d through the maintenance	o hala harri
1,				
hole. I understand that removal of call to	(owner's name), refuse	to allow the removal of so	olids and liquids through the	
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? exam	and liquids through other	er access points is not cons	sidered maintenance	maintenance
4. Is the tank designed as a leaky tank? exam Tank#1 Yes No Verificatio Meth	ווע פיביי אביבף ששל פינו, נפנגמסטו	, drywell, leaching pit		
Tank#2 Yes No Verificatio Meth	od Used:			
5 Is there evidence to	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	low the energy to the	
Tank	1	overs?	on the operating depth o	r evidence of
	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes PNo	Yes No	Yes No	-
Septic/Holding Tank #2	☐ Yes ☐ No	T Yes Two		-:
Pretreatment Tank	T Yes T No	☐ Yes ☐ No	Yes Jano	:
Pump Tank	Yes No	Yes No	Yes No	٠.
6. How many gallons of septage were remov	red?	[] 1C3 [_:140	Yes No	
Tank #1 (250) Tank #2 (000)	Pretreatment Ta	nk -		
7. Other information: List any troubleshooting	of minor remains	PU	mp Tank	
7. Other information: List any troubleshooting	's/ ''''illor repairs condi	icted, tank safety conce	rns, or other concerns.	
8. Certification: I hereby certify as a State of M and made the observations, or Maintainer's Name of the State of M.	Innesota certified SSTS N	Maintainer that I personall	y conducted the work	
Maintainer's Name: (755)		and performance of	this job.	
Maintainer's License #: 2 \\ Maintair		's Address: 17639	Lyms St	NE
Maintair	ner's Phone #: 444-	2080	1	
Maintainer's Signature		Date: 11-1-1	\circ	
		Date: (, '	1	