

OUTHURNELL CELLER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location							
Address 3320	Stagecoach	Thail	N	Telephone	e Number		
City StillWa		State M N Z	P55082	Property ID No.	/GEO Code		
Owner Tom	Wihren	Pumping Date	_ / /				
10111	Willes,	Contrac	tor				
Maintainer MEYE	RSEWER	MPCA License N	0. 915	Telephone	e Number 657-4	159-016	
What was		Report Liquid Capacity in Gallons					
Tank(s) Pumped		Tank 1: /2	00 Pumped	Tank 2:	Pumped		
Sludge and scum n		Tank 3:	Pumpec		Pumped		
Do tanks need to be pumped? Yes No (If no provide measurements below)			Total Gallons Pumped: 1200				
			NOTE: Thi	s does not sen	ve as a complianc	e inspection.	
visual inspection (/	note any problems with the	Jyseemj.					
		,					
	*Tank Measure	ments-Use Only	If Tank(s) Were	NOT Pumped			
Tank Length	in. X Tank Width	in. X Tank De	epth i	n. = Tank Volu	ıme (cubic inches)		
Tank Radius	in. X Tank Radius	in. X 3.14 :	= Tank Volum	e (cubic inches)			
Tank Volume (cu. in.)	/ 231.01 = L	- iquid Capacity	Gallo	ons / Tank Dept	h in. = Gallon	s/Inch	
Sludge Level	in. X Gallons Per Inch	= Sludge Vo	olume	Gallons			
		= Scum Vol		Gallons			
Scum Level	in. X Gallons Per Inch	— Scum voi	ume 	Ganons	C-11		
Sludge Volume	+ Scum Volume	= Total Slud	dge and Scum V	olume ———	Gallons		
Total Sludge and Scu	ım Volume / Li	quid Capacity	= Pei	rcent Sludge and	d Scum in Tank	% 	
				*Tanks i	must be pumped if	either of the	
				followir	ng conditions exist:		
Scum Layer		$\sqrt{1}$		1. The to 12 inch	op of the sludge lay es from the bottom	of the outlet	
Effluent	- 1	Tan	k Depth measur	baffle; o			
Linuent		- (<u> </u>	n invert of outle e to bottom of t	ank than 25	percent of the tan	k's liquid	
Sludge Layer		Pilo.	c to bottom or t	capacit	y.		
	11/1/2	Date	9/01	15	Reset F	orm	