		address: 9621 206th STreet North	n Forest Lake	Inspector initials/Date: SS 10/9/2019	
				(mm/dd/yyyy)	
1.	In	npact on Public Health – C	Compliance com	ponent #1 of 5	
		ompliance criteria:		Verification method(s):	
	Sy	stem discharges sewage to the	☐ Yes ⊠ No	Searched for surface outlet	
		ound surface.		Searched for seeping in yard/backup in home	
	Sy	stem discharges sewage to drain	☐ Yes ☒ No	☐ Excessive ponding in soil system/D-boxes	
	tile	e or surface waters.		☐ Homeowner testimony (See Comments/Explanation)	
		stem causes sewage backup into velling or establishment.	☐ Yes ⊠ No	☐ "Black soil" above soil dispersal system	
	Any "yes" answer above indicates the			System requires "emergency" pumping	
		stem is an imminent threat		Performed dye test	
	health and safety.			☐ Unable to verify (See Comments/Explanation)	
	-	omments/Explanation:		☐ Other methods not listed (See Comments/Explanation)	
	CC	mments/Explanation:			
2.	Ta	nk Integrity – Compliance	component #2 c	of 5	
	Compliance criteria:			Verification method(s):	
	Sv	stem consists of a seepage pit,	☐ Yes ⊠ No		
	ces	sspool, drywell, or leaching pit.	Lies Mino	Probed tank(s) bottom	
	Sec	epage pits meeting 7080.2550 may be		Examined construction records	
	cor	npliant if allowed in local ordinance.		⊠ Examined Tank Integrity Form (Attach)	
	Se	wage tank(s) leak below their	☐ Yes ⊠ No	Observed liquid level below operating depth	
		signed operating depth.		☐ Examined empty (pumped) tanks(s)	
	If y	es, which sewage tank(s) leaks:		☐ Probed outside tank(s) for "black soil"	
	Any "yes" answer above indicates the			☐ Unable to verify (See Comments/Explanation)	
	y y = = = = = = = = = = = = = = = = = =			☐ Other methods not listed (See Comments/Explanation)	
	12.00				
3.	Other Compliance Conditions - Compliance component #3 of 5				
	a.	Maintenance hole covers are damaged, cracked, unsecured, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unknown			
b Other income (statistical)			adversely impact public health or safety.		
	C.	System is non-protective of ground v*System is failing to protect ground	water for other cond	itions as determined by inspector . ☐ Yes* ☒ No	
		Explain:			
		-			

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31b • 6/4/14