



# Soil Observation Log

Project ID: v 04.01.2019

Client: **Robert Harrell** Location / Address: **9621 206th Street North Forest Lake**

Soil parent material(s): (Check all that apply)  Outwash  Lacustrine  Loess  Till  Alluvium  Bedrock  Organic Matter

Landscape Position: (check one)  Summit  Shoulder  Back/Side Slope  Foot Slope  Toe Slope  Slope shape

Vegetation: Lawn Soil survey map units: Slope %: Elevation:


Weather Conditions/Time of Day: Sunny 4:00 p.m. Date: 10/09/19

Observation #/Location: Soil boring by STA Observation Type: Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence
0-6	Loamy Sand	<35%	7.5YR 3/4				Granular	Weak	Loose
6-24"	Coarse Sand	<35%	10YR 4/6				Granular	Weak	loose
24-66"	Coarse Sand	<35%	10YR 5/4				Granular	Weak	Loose

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.


  
 (Designer/Inspector) \_\_\_\_\_ (Signature) \_\_\_\_\_ (License #) **1106** (Date) **10/9/19**