

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit n	nust be complete	
prior to perfor	ming maintenance activit	ies and remain on	-site for the durati	on of the maintenar	nce activity.	
Date of Maintenance:	2-12 - 19 Reason	for Maintenance:	Routin	_		
Property Address: 13	5820 23rd S	St. No	Property Owner's Na	ame: Etten (<u>Cunningha</u>	
Municipality:	hunto zip: 550	Property Ide	ntification Number:			
Maintenance Permit N	0.94903n17730	Maintainer Name a	nd License No. Pinky	y's Environmental Se	wer Service/ L167	
Maintena	nce Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		GL ULL THE THE STATE OF	Liquid Level of Tank — in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintena	nce Hole Other (enter authorization co	de)		
Were all covers see	curely replaced? Yes	□No				
	of tank leakage from a sep ged, cracked, or structur			/	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed					
Tank #1	gal Tank #2	_gal Pretreatmen	t tankga	l Pump Tank	gal	
	List any troubleshooting					
	disposal:					
		The production of the second		01		

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

F: 651-439-484/ Licen