## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entiret	y to constitute a	valid maintenance	permit. This permit	must be completed	
prior to pe	maintenance activ	ities and remain o	on-site for the dura	ation of the maintena	nce activity.	
Date of Maintenand	ce: 12-5-19 Reaso	n for Maintenance	Rastina		,	
Property Address:	10833 1141 8	37. Ma	Property Owner's	Name: Croica 1	Williams	
Municipality:	Muute zip: 55	Property Id	entification Numbe	r:		
Maintenance Permi	t No:23052g 17510	Maintainer Name	and License No. Pin	lou's Environment of S		
		, , , , , , , , , , , , , , , , , , ,	and Electise No. Fill	ky s Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		the state of the s	Liquid Level of Tank — in			
$\square$ Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to r	emove septage:   Maintena	ince Hole Other	enter authorization o	oda)		
	securely replaced? \( \square\) Yes		enter dutilonization c	ode)		
3. Is there evidence	e of tank leakage from a sep maged, cracked, or structur	otic, holding, pret	reatment or pump ntenance hole cove	tank below the opera	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	s of septage were removed?					
Tank #1 5200		gal Pretreatment	tankga	l Pump Tank	۳al	
Other information			and the second s	The state of the s		
too old	n: List any troubleshooting,	minor repairs cor	nducted, tank safet	ty concerns, or other	concerns.	
too old	n: List any troubleshooting,	minor repairs cor	nducted, tank safet	ty concerns, or other	concerns.	
700 OK 9	ter mushell					
700 OK 9	n: List any troubleshooting,  fer numbel  de disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001